
### DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

# WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-009746 Address: 333 Burma Road **Date Inspected:** 14-Oct-2009

City: Oakland, CA 94607

**OSM Arrival Time:** 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

**CWI Name:** Xu Yumin **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:** 

34-0006 **Bridge No: Component: OBG Segments** 

## **Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector, Dan Hernandez was present during the times noted above to observe the fit up, welding and related activities associated with the fabrication of the San Francisco Oakland Bay Self Anchored Suspension Bridge at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

**OBG Trial Assembly Yard** 

Segment 1AAE/1AE

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as OBE1-001. The welder is identified as #045138 and was observed welding in the 1G (flat) position using approved Welding Procedure Specification WPS-345-FCAW-1G (1F)-repair-1 for CWR814 UT reject.

Segment 1AW/1BW

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as OBW1A-007. The welder is identified as #220067 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-345-SMAW-4G (4F)-repair-1 for CWR831 UT reject.

## WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Segment 2AW

This QA Inspector observed Flux Cored Arc Welding (FCAW) in progress of a Plug weld joint. The welder is identified as #220066 and was observed welding in the 1G (flat) position using approved Welding Procedure Specification WPS-345-FCAW-1G-repair-Misdrilled Bolt Hole for CWR755.

This QA Inspector observed ZPMC personnel performing Magnetic Particle Testing on 6 UT reject excavations Side Plate segment splice, counter weight side.. Transverse indications were discovered in each excavation by ZPMC NDT technician. The excavations were at the following Y locations: 4790mm, 5080mm, 6490mm, 6750mm, 7540mm and 8680mm from the bottom plate.

Segment 5CE

This QA Inspector observed match drilling in progress of bolt holes in the Deck Plate U-ribs.

ZPMC Quality Control (QC) Inspector is identified as Feng Ya Jun. QA Inspector observed QC Inspector verify welding parameters. The welding variables recorded by QC appeared to comply with the Applicable WPS.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

## **Summary of Conversations:**

No relevant conversations.

### **Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372, who represents the Office of Structural Materials for your project.

| Inspected By: | Hernandez,Dan   | Quality Assurance Inspector |
|---------------|-----------------|-----------------------------|
| Reviewed By:  | Carreon, Albert | QA Reviewer                 |